## CERCLA REMOVAL ACTION DAILY WORK ORDER

•	CENCLA REI	NOVAL AC	HON DAILT WORK ORDER	
	DAILY WORK O	RDER		•
RESPONSE LOCATION (SITE NAME AND/OR ADDRESS AND ZIP CODE)  Digne Marive  which ington Street  Perth Amboy NJ			CONTRACT NO.	ORDER NO.
			68-02-6893	6893-02-017
			DATE TUESDAY	SHIFT
		_	December 11 1984	
	EPA REGION/USDG		ON-SCENE COORDINATOR	0 100
SITE/SPILL NO.	EPA REGION/USDO	ו פוט ג		SRAGUE
CONTRACTOR	H MATERIA	L S	CONTRACTOR RESPONSE MA	
1.			ITOR(S) N/A	
BRUCE SPAN	LE EPA			
JACH HARN	_	<del> </del>		
2.		TION OF WO	RK TO BE PERFORMED	•
	panse MANAGE			Wician
2) Repair or	BOARD UP U	Jindow 5	and ferce a	s designated
By By				
3) continue GVA	RO SERVICE FAR	m 1:	26-1/2/85	
(E) 1200050 ···	ill abbe a	- 10 =	HARGE AS AGRE	· · · · · · · · · · · · · · · · · · ·
EPD &	o Am.	<u> </u>	HARGE AS AGAE	ed upon between
<b>?</b>	NUMBER	OF PERSO	NNEL AUTHORIZED	
	-	FO	REMAN	OPERATORS
LABORERS		оті	HER (SPECIFY)	
4.	EQUIPMENT AND EX	KPENDABL	E MATERIALS AUTHORIZED	
LEM		CUANTITY	ITEM	QUANTITY
A TON TRUC			- purchase guth	PREATION -
5 Kw Genera			plymoon - 2"x4"	as needed
	<u> </u>			
	amplete)			
DANGER S	Signs			
AUTHORIZED BY THE COMMANCE OF THE ABOVE	CONTRACTOR IN TH	HE PER-	LACKNOWLEDGE RECEIPT	OF THIS WORK ORDER.
SIGNATURE OF OSC	· · · · · · · · · · · · · · · · · · ·		SIGNATURE OF CONTRACTO	R'S REPRESENTATIVE
Bruck lower	<u>.                                    </u>		Down Dealing	3 NEFRESENTATIVE
	AMENDMENTS	(INCLUDE	TIME AND AUTHORIZING PER	SON)
				•
				4

335039